File 13:102

Approved For Release 2002/06/13 : CIA-RDP81B00878R000600010226-0

CONTRACTOR NAME LAC

FURCHASE REQUEST NO.10-10-98

CONTRACT NUMBER SP 1917 or SP-1918

TIEM No.	PART NUMBER	NOM	PACK	STATUS CODE	TODAL OTY	unit Cost	ACCUMULATED COST
1.	473.1-SP-VS-743	Valve	EA	NR	50		The second secon
2.	158.8-SP-W-126-10	Pin-Hinge	EA	NR	17)	
3.	158.7-SP-W-126-9	Pin-Hinge	EA	NR	17		
4.	158.6-SP-W-126-8	Pin-Hinge	EA	NR	17		
5.	158.5-SP-W-126-7	Pin-Hinge	EA	NR	17	Bernard Control of the Control of th	managan ang ang ang ang ang ang ang ang a
6.	158.3-SP-W-10-65	Pin	EA	NR	17	la constanta de la cons tanta de la constanta de	· · · · · · · · · · · · · · · · · · ·
7.	158.2-SP-W-10-64	Pin	FA	NR	45	and and the second	and war foliation of positioning accepts introducen and in 1,816 for any 2014 is
8.	158.1-SP-W-10-63	Pin	EA	NR	17	The adjustification on a series were resident assessment as a series of the series of	
9.	156-SP-F-191	Plug	FA	NR	100		
10.	148-SP-L-1-5	Lockplate	EA (NR	26		
11.	484-SP-750-B-3	Valve	EA	NR	12		
12.	182.2-SP-L-144	Shim-Axle	EA	NR	90		100.26 ALZEN
13.	182.1-SP-F-529	Shade-Sun	EA	NR	15		
14,	176.2-SP-F-325	Seal	EA	NR.	50		
15.	174.2-SP-F402-16	Sea1	EA	NR.	8		
16.	172.1-SP-Q-120-11	Seal Cover	EA_	NR NR	25		
17.	171.1_SP=Q-120-10	Seal Cover	EA_	NR.	33 -		and the second
18.	164.2-SP-P-84	Restrictor	EA	NR	20		The following and to make the integral of the same of
19.	15 8. 12-SP-W-126-13	Pin-Hinge	EA	NR	17		Aller of the second sec
20.	158.11-SP-W-126-12	Pin-Hinge	EA	NR	20	A region and annual designation of the second	STATINTL

STATINTL

AUTHORIZED BY:

Approved For Release 2002/06/13 : CIA-RDP81B00878R000600010226-0

	LAC	PURCHASE	REQUEST	NO]	LO -1 0-98
CONTRACT NUMBER S	SP 101/				

ITEM NO.	PART NUMBER	MOLIN	UNIT PACK	STATUS CODE	TODAL QIY	unit Cost	ACCUMULATED COST
21.	158.9-SP-W-126-11	Pin-Hinge	F A	NR	14	ner aller Ton containings and the Art at Section	AND AND THE COMMENT OF THE COMMENT AND
22.	184_SP_L_92	Shim	EA	NR	30		ting the state of
23.	183-SP-I-56	Shim	EA	NR	30		Harman der 192 system der dem einem met den eine dem eine der eine der eine dem eine der eine der eine der ein
24.	190_SP_L_105	Spacer-Tail	EA.	NR	25		and the second s
25.	189_SP_Q_059	Spacer	E A	NR	30		The state of the s
26.	421_SP_15201_2	Separator	EA	NR	10	tanaka di Julia di Angara da A	The second secon
27.	398_SP_11351	Re g ulator	EA	R	10		Belleville (1995) and physics residentified in 1995, and an alternative (1995) and
28.	390.1-SP-1400B	Pump	EA	R	2		and the state of t
29.	335-SP-R-3800DD-162	Hose	EA	NR	20		and the state of t
30,	187-SP-Q-056	Slider-Assy	EA ,	NIR	12		and a second
31.	185A-SP-W-130-22	Sh ow -Wing	EA	NR I	16		
32.	334.1-SP-601000-4	Hose	EA	NIR	10		
33.	333.1-SP-601000-4	Hose	EA	NIR	10		
34.	330_SP_MS_28741-4	Hose	EA	NR	10	41	The state of the s
35.	329_SP_MS_28741_12	Hose	EA	NR	_10		generalised de la company
36.	319.3-SP-601000-12-0	460 Hose	EA	NR	5	······································	and the second section of the second section of the second section of the second section of the
37.	319,2-SP-601000-24-0	350 Hose	EA	NR	5	ign allgamen van den valer, valer minner vers en	The second secon
38.	255_SP_913B4	Capstan Auto Pilot	EA	NR	10	er meteodologica er en Siedense des	The parties and the same of th
39.	257-SP-10002Y-T2	Cap	EA	NR	1.4	of the Wildowskin of the Control of	The state of the s
40.	43-SP-P-3-15	Clamp	EA	NR	6		ATINTL

AUTHOR IZED	B¥ s_	

Approved For Release 2002/06/13: CIA-RDP81B00878R000600010226-0

CONTRACTO	R NAME	LAC	350 - 160 to -40
CONTRACT	NUMBER	SP 1914	\$145000

FURCHASE REQUEST NO. 10-10-98

PTEM NO.	PART NUMBER	NON	PACK	STATUS CODE	TOTAL QTY	UNIT	ACCUMULA TED COST
41.	251-SP-45-21790-13	Blanket	EA	NR	20		
42.	613_SP-1-766C	Compound	EA	NR	50		
43.	250-SP-45-21790-12	Blanket	EA	NR	15	·	
44.	252.3-SP-M6001B-1A	Blower	EA	NR	12		
45.	:252_SP_45_21790_14	Blanket	EA	NR	15		
46.	256,1-SP-CG-320/ARC	Cable	EA	NR	13		
47.	256.2-SP-CG-131/ARC	Cable	EA	NR	11		
48.	279-SP-42535-200SH	Coupling	EA	NR	11		
49.	278-SP-42535-150-SH	Coupling	EA	NR	15		The second secon
50.	282-SP - 711146	Coupling	EA	NR	28		and a district
51.	281-SP-42535-300-SH	Coupling	EA	NB.	15		
52.	307.1-SP-460-015-24	Gasket	EA	NR	77		
53.	303.1-SP-9522673	Gasket	EA	NR	50		
54.	319,1-SP-601000-402	O Hose	EA	NR	11_		
55.	318,2-SP-601000-24-	0090 Hose	EA	NR	_10	·	
56.	320.1-SP-MS-28741-4	-0245 Hose	EA	NR	10	, agradet per 19 -	
57.	325-SP-MS28741-4	Hose	· EA	NR_	28		A STATE OF THE STA
58.	333-SP-601000-4	Hose	EA	NR.	10	· agence description of the second	San A Characherson
59	331-SP-M 8 28742-4	Nose	EA	NR.	مد ا	na - Namara ni Garifeniya (nami	1. Application of the second s
60.	428_SP_42737_200	Sleeve	EA	NR	15	STA	TINTL

CONTRACTOR	NAME	LAC	milespania medicana an estrat
		SP 1914	

PURCHASE REQUEST NO. 10-10-98

TTEM NO.	PART NUMBER	NOUN	PACK	STATUS CODE	TOPAL QTY	unit	ACCUMULATED COST
61.	422.1-SP-LA2195-72	Shift	EA	NR	14		
62.	30-SP-P-16	Cap-Mount	EA	NR	10		A CONTRACTOR OF THE STATE OF TH
63.	38-SP-P-17	Cap-Mount	EA	NR	7	l'Alian del est estadia, p .	and the state of t
64/	37_SP_P-15	Cap-Mount	EA	NR	10		The state of the s
65.	35_SP_R_109_5	Cap-Light	EA	NR	11		Anthropia (Maria Maria Maria) (Maria Maria) (Maria) (M
66.	31-SP-R-109-3	Cap-Light	E ^A	NR	9		And the second of the second o
67.	20.1-SP-F-292.2	Boot Equipment	EA	NR	11		
68.	140-SP-P-66	Gasket	EA	NR	50	:	
69.	139-SP-F-116-3	Gasket	EA	N R	16		
70.	119.2-SP-F-429	Fitting	EA	NR	10		and the state of t
71.	54-SP-L-117	Cylinder	EA	NR	8		
72.	52_SP_L_126	Cylinder	EA	NR	8		and the state of t
73.	51-SP-H-5	Cylinder	EA	Nr	5		Bergeria sandaning dan saktuada saktur dan 1944 sadaran
74.	213-SP-P-9	Crunnion-Mount	EA	NR '	6	· ·	gant lights of well-stilling aggressed stillings or a garage or restaude algorithms.
75.	41-SP-303379	Cap	EA	NR	<u>1</u> 0		
76.	40-SP-P-24	Cap-Mount	EA	NR	9		The state of the s
77.	196.1-SP-H87-1	Strainer	. EA	NR	10		
78,	196-SP-H-55	Strainer	EA	NR	10		The same of the sa
79.	214-SP-P-13	Trunnion-Mount	EA	NR	6		A CONTRACTOR OF THE CONTRACTOR
80.	215-SP-L-1-3	Washer	EA	NR	135	STA	TINTL

AUTHORIZED	BY:	

CONTRACTOR NAME	LAC	PURCHASE	REQUEST	No. 10-10-98
CONTRACT NUMBER	SP 1914			

NO. PART NUMBER NO. NO. PACK CODE CTY COST ACCURULATED	*****			-,		-	-	
82. 222.1-SP-F-29-25 Zee-Bulkhead EA NR 47 83. 221-SP-L-142 Wire-Ground EA NR 32 84. 239.1-SP-12-21917 Blanket E ^A NR 23 85. 233-SP-47532-3 Amplifier EA NR 10 86. 245-SP-45 Blanket EA NR 15 87. 244-SP-45-21790-6 Blanket-Tailpipe EA NR 15 88. 247-SP-45-21790-9 Blanket EA NR 17 89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	-	PART NUMBER	NOON		1	1 1		
83. 221-SP-L-142 Wire-Ground EA NR \$2 84. 239.1-SP-12-21917 Blanket E ^A NR 23 85. 233-SP-47532-3 Emplifier EA NR 10 86. 245-SP-45 Blanket EA NR 15 87. 244-SP-45-21790-6 Blanket-Tailpipe EA NR 15 88. 247-SP-45-21790-9 Blanket EA NR 17 89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	81.	214.1-SP-H-39-18	Tube	EA	NR	44		
84. 239.1-SP-12-21917 Blanket E ^A NR 23 85. 233-SP-47532-3 Amplifier EA NR 10 86. 245-SP-45 Blanket EA NR 15 87. 244-SP-45-21790-6 Blanket-Tailpipe EA NR 15 88. 247-SP-45-21790-9 Blanket EA NR 17 89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	82.	222.1-SP-F-29-25	Zee-Bulkhead	EA	NR	47		
85. 233-SP-47532-3	83.	221-SP-L-142	Wire_Ground	EA	NR	8 2		
86. 245-SP-45 Blanket EA NR 15 87. 244-SP-45-21790-6 Blanket-Tailpipe EA NR 15 88. 247-SP-45-21790-9 Blanket EA NR 17 89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	84.	239.1-SP-12-21917	Blanket	EA	NR	23		
87. 244-SP-45-21790-6 Blanket-Tailpipe EA NR 15 88. 247-SP-45-21790-9 Blanket EA NR 17 89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	85.	233-SP-47532-3	Amplifier	EA	NR	10		
88. 247-SP-45-21790-9 Blanket EA NR 17 89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	86,	245-SP-45	Blanket	EA	NR	15		
89. 246-SP-45-21790-8 Blanket EA NR 14 90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	87.	244-SP-45-21790-6	Blanket-Tailpipe	/ EA	NR	15		
90. 249-SP-45-21790-11 Blanket EA NR 15 248-SP-45-21790-10 Blanket EA NR 15	88.	247-SP-45-21790-9	Blanket	EA	NR	17		
248-SP-45-21790-10 Blanket EA NR 15	89.	246-SP-45-21790-8	B la nket	EA	NR	14		
	90.	249-SP-45-21790-11	B la nket	EA	NR	15		
92 386.35p.5548165 PLug BA N/R 400	248-9	SP-45-21790-10	B la nket	EA	NR	15		
	92	386.359.5548165	PLug	BH	NK	400		
								
	And delivery spiritely from the spiritely from the				1	+		
						<u></u>		

				ERE A COLOR				
	-							-

]. -					_
N. Carlotte	or, where the state of the stat				
AUTHORIZED EX:			<u>.</u>		

FILE

1059

IAC 10-17-102

SP-1917 or SP-1918

F293-10		ea	n/r	3	r/a	
F293-11		PA	tt .	3	#4	
F293-12		BA	17	3	†1	
P-85	Bushing	EA	69	48	FI	
P-90-u	Tube Assy	EA	*1	15	41	
P-78-2	Tube Assy	EA	\$ \$	12	41	
P-78-3	Tube Assy	EA	Ħ	15	53	
P-78-4	Tube Assy	EA	n	12	**	
P-78-7	Tube Assy	EA	Ħ	12	16	
P-78-8	Tube Assy	EA	**	12	0	
P-78-9	Tube Assy	EA	C #	12	Et	
P-78-10	Bracket	EA	e	12	19	
P-78-11	Clip	EA	es es	12	17	
NAS 501-7-40A	Bolt	EA	u	als	83	
NAS-431103-80	Spacer	EA	71	12	të	
LS4634-5	Gesleet	EA	n	15	11	
MS29512-5	Gasiert	EA	#	12	**	
P-86	Fire Shield	ea	88	12	Ħ	
	Tube Assy	EA	47	12	H	= 0.15
P-78-12 P-78-13	Tube Assy	FA	e)	12	77	ILLEGIB
- 1 -		······································	Γ			

Approved For Release 2002/06/13: CIA-RDP81B00878R000600010226-0

FILE

1059

LAC

10-17-102

1914

2	P-78-14	Tube Assy	ea	n/R	15	n/a
2	P-78-15	Bracket	EA	**	12	Ħ
2	206292	Brechet	EA	#	12	41
2	NAS517-5-2	Screv	EA	Ħ	a+	ti
2	140223-4	Screv	EA	77	24	\$2
2	MAS517-5-4	Berew	EA	17	75	7.0
2	P-50-8	Clip	EA	11	15	87
2	P-84	Resistor	ea	Ħ	12	£9
2	A1901-4A	Washer:	EA	47	12	11

NOTE: Items 1, 2 & 3 are spares for SE211 as per recommendation from Contractor

ILLEGIB